

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

1522
East
> 1
1.909 mi.
10077 ft.

BETWE BEDFORD EA 26TH
2511 EMMONS AVE
BROOKLYN, NY

NY Spills S106699187
N/A

Relative:
Higher

Actual:
5 ft.

SPILLS:

Name: BETWE BEDFORD EA 26TH
Address: 2511 EMMONS AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0406443 / 2004-09-14
Facility ID: 0406443
Facility Type: ER
DER Facility ID: 99954
Site ID: 114608
DEC Region: 2
Spill Cause: Unknown
Spill Class: D5
SWIS: 2401
Spill Date: 2004-09-12
Investigator: JMKRIMGO
Referred To: Not reported
Reported to Dept: 2004-09-12
CID: 41
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Health Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2004-09-12
Spill Record Last Update: 2004-09-14
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
KRIMGOLD "
Remarks: "Unknown type oil in water at fishing dock - dead fish - caller was
anonymous"

All Materials:

Site ID: 114608
Operable Unit ID: 889996
Operable Unit: 01
Material ID: 487518
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

Site ID: 114608

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Operable Unit ID: 889996
Operable Unit: 01
Material ID: 487519
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: L
Recovered: .00
Oxygenate: Not reported